

State of Connecticut  
**CONNECTICUT HISTORICAL COMMISSION**  
59 South Prospect Street, Hartford 06106

**HISTORIC RESOURCES INVENTORY:**  
Buildings & Structures

**SURVEY OF GUILFORD, NEW HAVEN COUNTY, 06437**  
June-December 1981

FOR OFFICE USE ONLY	
Town No.:	Site No.: 444
UTM	
QUAD:	
DISTRICT	IF NR SPECIFY
<input type="checkbox"/> S <input type="checkbox"/> NR	<input type="checkbox"/> Actual <input type="checkbox"/> Potential

IDENTIFICATION

1. ADDRESS 456 Whitfield Street  
(map 26, lot 29)
2. NAME Caleb Benton  
(historic)  
NAME  
(common)
3. USE  
(historic)  
USE Private house  
(present)
4. IF MOVED, WHEN AND FROM WHERE:



DESCRIPTION

5. ARCHITECT
6. DATE 1865
- BUILDER William Weld  
STYLE Greek Revival
7. ALTERATIONS  
Shingle siding; side wing; 6/6 sash (first floor); porch (shed, roof, square columns).
8. NOTABLE FEATURES  
6/6 sash (second floor); rectangular gable window; pilasters flank the front door.

SIGNIFICANCE

9. ARCHITECTURAL-HISTORICAL  
The Caleb Benton home is one of the sizable group of Greek Revival houses in Guilford built by William Weld. Wooden shingle is an unusual wall treatment for houses of this sort; probably early 20th century alteration. This house is a reminder of the rural heritage of this part of town from its site atop a hill.

SOURCES

10. SOURCES  
Dorothy Whitfield Society '76; William Weld ledger.

In all categories below, check more than one box if applicable.

If you have not actually made certain of the answer to a given question, either leave it blank or write "inferred" after the checked box; or, if drawn from a previous investigator, give source.

11. MATERIALS

- |  |                                     |                                      |   |                                 |
|--|-------------------------------------|--------------------------------------|---|---------------------------------|
| <input type="checkbox"/> Clapboard               | <input type="checkbox"/> Brick      | <input type="checkbox"/> Stucco      | <input type="checkbox"/> Asbestos Shingle | <input type="checkbox"/> Other: |
| <input checked="" type="checkbox"/> Wood Shingle | <input type="checkbox"/> Fieldstone | <input type="checkbox"/> Concrete    | <input type="checkbox"/> Asphalt Siding   |                                 |
| <input type="checkbox"/> Board & Batten          | <input type="checkbox"/> Cut Stone  | <input type="checkbox"/> Cobblestone | <input type="checkbox"/> Aluminum/Vinyl   |                                 |

12. STRUCTURE

- |                                      |                                  |  |                                   |                                 |
|--------------------------------------|----------------------------------|--|-----------------------------------|---------------------------------|
| <input type="checkbox"/> Wood Frame: | <input type="checkbox"/> Masonry | <input type="checkbox"/> Iron or Steel | <input type="checkbox"/> Concrete | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Post & Beam |                                  |  |                                   |                                 |
| <input type="checkbox"/> Balloon     |                                  |  |                                   |                                 |

13. ROOF

- |  |   |                                   |   |                                 |
|--|---|-----------------------------------|---|---------------------------------|
| a. <input checked="" type="checkbox"/> Pitched | <input checked="" type="checkbox"/> Gable-front     | <input type="checkbox"/> Hip      | <input type="checkbox"/> Shed           | <input type="checkbox"/> Other: |
| <input type="checkbox"/> Saltbox               | <input checked="" type="checkbox"/> Cross-gable     | <input type="checkbox"/> Flat Hip | <input type="checkbox"/> False Dormer   |                                 |
| <input type="checkbox"/> Gambrel               | <input type="checkbox"/> Mansard                    | <input type="checkbox"/> Flat     | <input type="checkbox"/> Sawtooth       |                                 |
| b. <input type="checkbox"/> Tower(s)           | <input type="checkbox"/> Monitor                    | <input type="checkbox"/> Cupola   | <input type="checkbox"/> Dormered Gable | <input type="checkbox"/> Dome   |
| c. <input type="checkbox"/> Wood Shingle       | <input checked="" type="checkbox"/> Asphalt Shingle | <input type="checkbox"/> Slate    | <input type="checkbox"/> Metal          | <input type="checkbox"/> Other: |

14. NUMBER OF STORIES:

2 1/2

APPROXIMATE DIMENSIONS:

LOT SIZE: approx. 1 acre

15. CONDITION: Exterior

- |                                    |  |                               |                               |                              |
|------------------------------------|--|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input checked="" type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|--|-------------------------------|-------------------------------|------------------------------|

16. CONDITION: Structure

- |                                    |                               |                               |                               |                              |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|
| <input type="checkbox"/> Excellent | <input type="checkbox"/> Good | <input type="checkbox"/> Fair | <input type="checkbox"/> Poor | <input type="checkbox"/> Bad |
|------------------------------------|-------------------------------|-------------------------------|-------------------------------|------------------------------|

17. OUTBUILDINGS (visible from public road)

- |   |   |  |                                  |                                  |
|---|---|--|----------------------------------|----------------------------------|
| <input checked="" type="checkbox"/> Barn(s)           | <input type="checkbox"/> Carriage House | <input checked="" type="checkbox"/> Garage | <input type="checkbox"/> Shed(s) | <input type="checkbox"/> Shop(s) |
| Other (well, stand, greenhouse, gazebo, privy, etc.): |   |  |                                  |                                  |

18. LANDSCAPING (visible from public road)

- |   |  |                                     |                                      |                                 |
|---|--|-------------------------------------|--------------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Planted Grounds | <input type="checkbox"/> Garden        | <input type="checkbox"/> Terracing  | <input type="checkbox"/> Plaza       | <input type="checkbox"/> Court  |
| <input type="checkbox"/> Stone Wall(s)              | <input type="checkbox"/> Pickett Fence | <input type="checkbox"/> Iron Fence | <input type="checkbox"/> Post & Rail | <input type="checkbox"/> Other: |

19. SURROUNDING ENVIRONMENT

- |  |  |   |
|--|--|---|
| a. <input checked="" type="checkbox"/> Town Street                                   | b. <input checked="" type="checkbox"/> Commercial    | c. <input checked="" type="checkbox"/> Open |
| <input type="checkbox"/> Rural   | <input type="checkbox"/> Industrial                  | <input type="checkbox"/> Wooded             |
| <input type="checkbox"/> Semi-rural  | <input type="checkbox"/> Agricultural                | <input type="checkbox"/> Lakefront          |
| <input checked="" type="checkbox"/> Clustered Growth                                 | <input checked="" type="checkbox"/> Residential      | <input type="checkbox"/> Coastal            |
| <input type="checkbox"/> Development   | <input type="checkbox"/> Vacation, now or originally | <input type="checkbox"/> Salt marsh         |
| d. <input checked="" type="checkbox"/> Of outstanding scenic/architectural value     |  |   |
| <input checked="" type="checkbox"/> Of scenic/architectural value                    |  |   |
| <input type="checkbox"/> Of supportive value to contiguous scenic/architectural area |  |   |
| <input type="checkbox"/> Neutral   |  |   |
| <input type="checkbox"/> Other:  |  |   |

20. ROLE OF BUILDING IN ENHANCING QUALITY OF ENVIRONMENT

- |   |                                    |                                     |                                  |                                 |
|---|------------------------------------|-------------------------------------|----------------------------------|---------------------------------|
| <input checked="" type="checkbox"/> Vital | <input type="checkbox"/> Important | <input type="checkbox"/> Supportive | <input type="checkbox"/> Neutral | <input type="checkbox"/> Other: |
|---|------------------------------------|-------------------------------------|----------------------------------|---------------------------------|

21. OWNERSHIP

- |                                 |   |  |
|---------------------------------|---|--|
| <input type="checkbox"/> Public | <input checked="" type="checkbox"/> Private | <input type="checkbox"/> Interior accessible |
|---------------------------------|---|--|

INDEX NO. 444

22. Name

P. Odwin

Date 7/23/81

Photographer

P. Odwin

Date 7/23/81

Negative Roll 17:25

Organization:

Guilford Preservation Alliance  
P.O. Box 199, Guilford, Conn. 06437

Glfd's Neg. Roll 17:23a

23. THREATS TO BUILDING

- |                                     |  |  |                                     |                                 |
|-------------------------------------|--|--|-------------------------------------|---------------------------------|
| <input type="checkbox"/> None Known | <input type="checkbox"/> Highways      | <input type="checkbox"/> Vandalism     | <input type="checkbox"/> Developers | <input type="checkbox"/> Zoning |
| <input type="checkbox"/> Renewal    | <input type="checkbox"/> Private Owner | <input type="checkbox"/> Deterioration | <input type="checkbox"/> Other:     |                                 |

24. SUBSEQUENT EVALUATIONS